

ITHESELTINE. BAKESTONES (MIDDLE TRGET)

A. Dunbar 'The Haven' Middle St

Cent Alorton 3 West Street

Barrie Stevens Trumbleby Cottage

Ian Herring Gayle House Farm.

NORTH YORKSHIRE
RICHMONDSHIRE
5339

NZ 1207-1307

GAYLES

EAST STREET
(east side)

15/29

The Grange ✓

-

II

Farmhouse. Early-mid C19. Coursed rubble sandstone with ashlar dressings, Welsh slate roof. 2 storeys, 3 bays. Chamfered rusticated quoins. Central 6-panel door below overlight in ashlar surround with cyma reversa brackets supporting frieze and cornice. 16-pane sash windows in raised ashlar surrounds. Ashlar coping. End stacks, ashlar to left, brick to right. Windows have shutters with fielded panels.

NZ 1207-1307

GAYLES

MIDDLE STREET
(east side)

15/30

Town Farmhouse

-

II

Farmhouse. Late C18 - early C19, possibly of 2 builds. Rubble sandstone with some ashlar dressings, pantile and Welsh slate roofs. 2 storeys with rear outshut, 1:3 bays. Main house, to right: coursed rubble with ashlar dressings; chamfered rusticated quoins; central 3-panel door below 3-pane overlight in raised ashlar surround; sash windows with glazing bars in raised ashlar surrounds; shaped kneelers, ashlar coping; corniced ashlar end stacks. To left, lesser range, set back slightly and with slightly lower eaves level has 4-pane sash window with deep lintel; first-floor side-sliding sash; shaped kneeler, ashlar coping and ashlar end stack to left; pantile roof with stone slates at eaves. At junction of 2 ranges, quoined single-storey, lean-to porch with small window, and board door in left return.

NZ 1207-1307

GAYLES

MIDDLE STREET
(east side)

15/31

Manor House

4.2.69

GV

II

House. Very late C17 and very early C18. Coursed sandstone rubble with ashlar dressings, artificial stone slate roofs. 2 storeys, L-shaped plan, with main C18 range of 5 bays, and irregular C17 range at right angles. Main range: west elevation: ashlar plinth, rusticated quoins and first-floor band. Central early-C18 8-panel door with original wrought-iron door furniture, below 4-pane overlight in bolection-moulded ashlar architrave. 24-pane sash windows with thick glazing bars and small panes of crown glass in keyed ashlar architraves with moulded sills. Cyma reversa ashlar cornice. Shaped kneelers, ashlar coping. End stacks, that to left stepped and external. Projecting forward from left end of building a 2-storey wing, most of which is a C20 remodelling of an older single-storey range and not of special interest, but bay nearest main range, containing the staircase, is of special interest, and on its right return has tall round-arched staircase sash window with radial glazing bars, in keyed architrave with large cornice capitals. Rear, main range: central blocked ashlar doorcase with architrave jambs with chamfered banded rustication to their outer sides, and extended lintel with tripartite keystone and jewelled motifs in outer corners; 2 bays of C20 24-pane sash windows. To right, gabled end of older range has glazed door in plain ashlar surround and to its right an external stack. Left return of older range: on each floor a tripartite sash window in hollow-bolection-moulded keyed architrave, and to their right on each floor a small window; ashlar coping. Left return of staircase wing: portico with unfluted Doric columns supporting Tuscan frieze with blocking course above. Interior: William-and-Mary style doors of 6 fielded panels, the central panels being the smallest, and matching window shutters; main ground-floor rooms have early C19 ceilings with marginal decoration which indicates that a cross-passage was then formed from the front door, with reeded decoration to passage and room to left, and acanthus scrolls to room to left; dogleg staircase with elaborately turned balusters; first-floor saloon has bolection-moulded panelling, and moulded cornice which breaks forward over west windows.

6x

NZ 1207-1307

GAYLES

MIDDLE STREET
(east side)

15/32

Front railings, walls,
gateposts and gate piers
to the Manor House
(formerly listed as Gate
piers at Manor House)

4.2.69

GV

II

Railings, walls, gateposts and gate piers. Early C18 and C19. Wrought-iron railings, sandstone ashlar gate piers, coursed rubble walls. At north end of front railings, C18 ashlar pier with banded rustication to front and back, and cornice (top overgrown with ivy and not visible). Low wall with canted coping supporting plain railings with pointed bars, interrupted in centre by 2 smaller gateposts, circular in plan and shaped like cannon, and with ball finials. Modern wrought-iron gate not of special interest. The corresponding large gate pier at the south end of the railings only survives in its lowest courses, the rest having been replaced during the remodelling of the south-east wing. Included for group value.

NZ 1207-1307

GAYLES

MIDDLE STREET
(south end)

15/33

Gayles Hall and attached
garden wall
(formerly listed as
Gayles Hall)

19.12.51

GV

II

Fortified house, now farmhouse divided into two and outbuildings, with attached garden wall. Probably C16, with early C17, early C18 and later alterations. Some work for the Wycliffe family. Rubble with ashlar dressings, stone slate roofs. 2 storeys, irregular H plan, the 2 south-east wings probably once of 3 storeys. South-east elevation, with 2 cross wings: 1:3:1 first-floor windows. Quoins to wings. Between second and third first-floor windows of spine: centrally-hinged door of 6 fielded panels in ashlar architrave with bases, plain frieze and cornice; C20 casement window in former door opening on ground floor to left, and to right of present door the relieving arch of another opening. Sash windows with glazing bars in ashlar keyed architraves with moulded sills, and with scars or part-surrounds of mullion windows, those in wings with relieving arches of rubble voussoirs above. One window on each floor of wings, and one on ground floor of spine to left. Gables of wings have ashlar coping. Fluted lead rainwater heads at angles of wings with spine. Chimneys at outer and inner sides of wings. Right return of left (west) wing: on ground floor, part surround of mullion window; on first floor, blocked 3-light mullion window. Left return of right (east) wing: on ground floor, C20 6-panel door in C20 chamfered ashlar surround and to its left a C20 9-pane unequally hung sash window in C20 ashlar surround, both below an old relieving arch; on first floor part of a mullion window. Rear: spine: on ground floor, 6-pane sash window with part of a larger moulded sill and part of an C18 architrave used as a lintel; to its right a blocked single-light window; on the first floor, a stepped external stack supported on 4 ovolo corbels and fluted lead rainwater heads in angles. Left (east) wing: quoins, and quoins two-thirds of way along indicating width of wing before C18 staircase added; central part-glazed door in C19 ashlar surround with cornice, and relieving arch above; on first floor, sash window as before; to right, in extension, round-arched staircase window with thick glazing bars in surround with moulded sill and architrave to arch resting on impostes and with tripartite keystone; to the right return, a small ground-floor casement window and a first-floor blocked mullion window. Right (west) wing has board door in ogee-moulded chamfered quoined ashlar surround below relieving arch, large ridge stack, and to left (inner) return parts of mullion windows. Right return: ground floor, from left: 2-light chamfered mullion window below relieving arch; tripartite window with ashlar surround, the central light a sash with glazing bars, the outer lights fixed, below segmental relieving arch; blocked mullion window below relieving arch. First floor: in centre, part surround of mullion window; sash window with glazing bars on moulded sill; towards the left end, an eaves stack. Left return: chamfered ashlar doorway and mullion windows. Running approximately 8 metres north-east from north-east corner of rear right (east) wing, rubble garden wall with ashlar coping, swept down to north-east, and with basket-arched quoined chamfered

Continued

Gayles Hall and attached garden wall continued

ashlar doorway at west end. Interior: reeded coving to cornices in ground-floor rooms of east wing; doors and linings of 6 fielded panels; added to north end of east wing, early C18 oak dogleg staircase with turned balusters with gadroon on vase, wreathed handrail and panelled dado; in eastern room of spine, early C17 decorated plaster ceiling, originally part of a larger room divided up by thick beams into 9 panels with circular motif in centre panel, with fretwork, guilloche and flower motifs, each panel richly corniced. From 1563 to 1821 Gayles Hall was the seat of the Wycliffe family. North Yorkshire and Cleveland Vernacular Buildings Study Group Report No 793.

NZ 1207-1307

GAYLES

MIDDLE STREET
(south end)

15/34

Coach-house approximately
10 metres north-east of
Gayles Hall

GV

II

Coach-house and stable block. Late C18 - early C19. Coursed rubble, stone slate roofs. 2 and 1 storeys. Central 2-bay, 2-storey coach house flanked by single-storey, 3-bay stables. Coach house: projecting slightly; quoined segmental-arched openings in dressed stone with leaved board doors with single window above; coped gable and apex chimney. Stable ranges each have quoins to outer ends; a central board door in chamfered quoined surround flanked by slatted windows with thin lintels and projecting sills. Interior: in stables 3 round-arched mangers in rear wall; queen-strut roof trusses. Included for group value.

NZ 1207-1307

GAYLES

MIDDLE STREET
(south end)

15/35

Barn approximately
60 metres north-west of Gayles
Hall

GV

II

Barn. Early C18 barn with early C19 addition. Coursed rubble, stone slate and corrugated sheet roofs. L-shaped plan with rear wing to right. 2 storeys, 5 internal bays, and with lower hexagonal gingang to right. Quoins. Central chamfered quoined doorway with pitching door above. 3 slit vents on each floor on either side. Shaped kneelers, ashlar coping. Rear facets of gingang roof of corrugated sheet. Interior: collared principal rafter roof trusses.

* NZ 1207-1307

GAYLES

WEST STREET
(east side)

15/36

Bay Horse Inn

4.2.69

GV

II

Inn. Late C17 - early C18. Rubble, artificial stone slate roof. 2 storeys, 2 first-floor windows. Quoins. Central door of 6 fielded panels in chamfered ashlar surround. On each floor two 3-light double-chamfered mullion windows. In the wall are wrought-iron tethering hooks. Ashlar coping. Rebuilt end stacks. To left, C20 single-storey lavatory block not of special interest; to right, C20 lean-to outbuilding not of special interest. Rear: plain ashlar door surround; ground-floor, 2-light chamfered mullion window; double-chamfered cross-window to staircase; flush ashlar first-floor window surround.

NZ 1207-1307

GAYLES

WEST STREET
(east side)

15/37

Belmont House

GV

II

House. Early C19. Coursed sandstone, stone slate roof. 2 storeys, 2 bays. Quoins. Central 6-panel door below 4-pane overlight in keyed ashlar surround. Windows have deep lintels and projecting sills, 16-pane sashes to left, 4-pane sashes to right. Ashlar coping. Left end stack.

NZ 1207-1307

GAYLES

WEST STREET
(east side)

15/38

West View
(formerly listed as
Cottage dated 1686
adjoining No 2 to north-
east)

4.2.69

GV

II

House. Dated 1686, but with unsympathetic alterations in 1968. Rubble, stone slate roof. 2 storeys, 2 first-floor windows. Central part-glazed door in chamfered quoined ashlar surround with triangular soffit to lintel and small recessed panel on lintel with raised characters "1686 TB". C20 3-light casement windows in concrete surrounds. Ridge stack to left of door and stack to rear of ridge at left end. Included for group value.

NZ 1207-1307

GAYLES

WEST STREET
(east side)

15/39

Pleasant View

GV

II

2 cottages, now one house. Late C18. Rubble, stone slate roof. 2 storeys, 2 first-floor windows. Quoins. In centre, paired flush ashlar door surrounds, that to left blocked, that to right with C20 part-glazed door. 4-pane sash windows with deep lintels and projecting sills. Shaped kneelers, ashlar coping. Ashlar end stacks.

NZ 1207-1307

GAYLES

WEST STREET
(west side)

15/40

Gayles House

4.2.69
GV

II

House, now farmhouse. Early C19 rebuilding of earlier house. Coursed dressed stone, Westmorland slate roof. L-shaped plan. 2 storeys plus cellar below front rooms, 3 bays. Quoins. Central door of 6 fielded panels below fanlight with decorative glazing bars in ashlar surround with paterae on cavetto brackets supporting open pediment. Sash windows with glazing bars with ashlar projecting sills and flush monolithic lintels scored as if of separate voussoirs. First-floor band. Roof hipped to right. Stacks rise from ridge over first bay of windows and from behind third bay. Single-storey lean-to outbuilding to right not of special interest. In rear wall of kitchen wing, projecting from rear right of plan, blocked tall pointed-arched opening; in right return of wing, 2 blocked round-arched windows. Left return: rendered; round-arched landing window with radial glazing bars. Interior: inside of front door has egg-and-dart motif carved round panels; other interior doors of 6 fielded panels; in kitchen in rear wing, tripartite ashlar fireplace with coved mantelshelf, and stone newel staircase in left corner beside fireplace; to rear left, behind sitting room, cantilevered stone staircase with moulded treads and wrought-iron stick balusters with wreathed handrail, leading to flagged first-floor passage supported on vaulted ceiling to ground-floor passage below. A house on the site was used as a school in the mid C18, and in the early C19 belonged to the Hird family who had a brewery in the outbuildings behind the house. North Yorkshire and Cleveland Vernacular Buildings Study Group Report No 767.

NZ 1207-1307

GAYLES

WEST STREET
(west side)

15/41

Front garden wall and
railings at Gayles House

GV

II

Garden wall and railings. Early C19. Wall of coursed stone more roughly dressed than front of house; wrought-iron railings. Wall is swept down in stages from left, and forms quadrant to right. Railings have spiked bars. In front of front door of house, 2 square piers with impost and pyramidal caps.

NZ 1207-1307

GAYLES

WEST STREET
(west side, off)

15/42

Hay Barn approximately
60 metres north-west of
Gayles House

II

Hay barn. Early-mid C19. Ashlar sandstone, stone slate roof. 2 storeys, 3 bays. Quoins. 3 arches in the front rise the full height of the building and are linked by impost band, the centre arch segmental in shape, the outer arches semicircular. Hipped roof.
